## **President Randy 3 CB Radio Service Menu Information**

## How to enter the menu:

- 1. Ensure the Radio is turned off.
- 2. Press and hold the [ANL/NB] button.
- 3. Press and hold the [Scan] button.
- 4. Turn the Radio on and release depressed buttons.
- 5. Use the [Up] and [Down] channel selection buttons to move between options.
- 6. Press and hold the [PTT] button and use the [Up] and [Down] channel selection buttons to change values.
- 7. Remember that lowering the values for power increases the power output! 😊



## Menu options and values:

Option	СН	Information
PWR-HI **	05	FM Expanded High-Power Adjustment [My standard value = 02-78]  ** only available when the radio is expanded / modified and powered from the car kit**
PWR-MI **	06	FM Standard High-Power Adjustment [My standard value = 03-07]  ** high power mode in un-expanded mode and when running on battery**
PWR-LO	07	FM Low Power Adjustment [My standard value = 03-42]
FM-MOD	09	FM Modulation [My standard value = 05-11]
AM-LO	13	AM LP Amplitude Adjustment [My standard value = 00-89] Ensure AM channel selected. 1.25K – 30mV. Adjust to 88%  This is amplitude adjustment not power. If you don't have the appropriate equipment to test leave this alone.
АМ-НІ	14	AM HP Amplitude Adjustment [My standard value = 01-08] Ensure AM channel selected. 1.25K – 30mV. Adjust to 86%.  This is amplitude adjustment not power. If you don't have the appropriate equipment to test leave this alone.
VER	21	Version number displayed VER122 = 1.22 In expanded mode VER122E = 1.22Expanded

Making alterations in the service menu could damage your radio or could be illegal in your region. Do not access the menu and / or make changes if you don't have the appropriate test equipment or knowledge. Changes and adjustments made at owner's own risk. Values above determined during testing and with reference to other President service manuals. This is un-official information and is provided on an "as is" basis. I / we will not be held responsible or accept any liability for any damage or issues encountered. © NLK Media 2022